

Work Order ID 151571

Tuesday, October 04, 2016 8:04:33 AM

151571

Page 1

Item ID: D205-596-105 USED

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Fwd Crosstube - Extended Height 31"

Start Date: 10/3/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 10/4/2016 Req'd Qty: 1.00

1

Customer: CMOUN02

Reference: RMA RA112386

Approvals: Process Plan: Em

Date: 16/10/04

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

100

0.00

100

QC

Memo

0.00

Quality Control

INSPECT RA112386

1 X D205-596-105 B23514

SCRAP/DESTROY PER INSPECTION SHEET

DAS
9
9-89

① 16-10-07

** cross tube will
be use for further
evaluation **

Ø Em 16/10/12.

Picklist Print

Page 1

Tuesday, October 04, 2016 8:05:53 AM

Work Order ID: 151571

151571

Parent Item: D205-596-105 USED

D205-596-105 USED

Parent Item Name: Fwd Crosstube - Extended Height 31"

Start Date: 10/3/2016

Required Date: 10/4/2016

Start Qty: 1.00

Required Qty: 1.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D205-596-105 USED

Manufactured

No

Each

0.0000

1

D205-596-105 USED

323514 @ 16007

Fwd Crosstube - Extended Height 31"

DAS
9
9-89

Inspection Sheet Complete **RA112386**

Customer QA Ref #

9528

Part Number	Batch / Serial #	Quantity	Part Complete	Rev/CHG Current	New Paperwork	New Labels	Disposition	Work order #	Work order instructions
D205-596-105	B23514	1	☐ Yes	☐ Yes	☐ Yes	☐ Yes	DAMAGED/SCRAP	151571	Cracks found at location of supports, and excessive damage found top of support. Sent tube to exova for x ray. No removal tag received
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			

QC Approval: P.D.

Date: 28-Sep-16